

**Stick Welding - Arc Welding
AND
M.I.G. (Metal Inert Gas) WELDING**

All classes meet at Mirabella-Finch studio from 9:00 am. to 12:30 pm

Required Materials

***(These items MUST BE BROUGHT TO EACH CLASS)**

***Long cuff leather gloves** (overall length 11” to 14”) Buy cheap ones because they will get destroyed in time. Gloves are available at any welding supply store. (Look in yellow pages under welding supplies) Home Depot, Lowes, Harbor Freight, Tractor Supply or similar stores also have gloves. Cheap Gloves at Harbor Freight (last store in Kroger strip mall across from Augusta Mall)

***Long sleeve shirt** (Cotton or Denim) with buttons on cuffs and top button at collar

***Leather shoes** preferably high tops or boots (not loafers).

***Long pants** without frayed places (Jeans are best)

***Anyone with long hair MUST have a tie back**

***Clear Plastic Safety glasses** to protect your eyes from grinding sparks (if you wear regular glasses make sure that you buy safety glasses that fit comfortably over your glasses)

***If you use reading or computer glasses, bring them.** You will need to see clearly at a distance of 16 to 20 inches.

***Hearing protectors**, either the insert plugs or over the ear muff-cup type. Either type are available at available at Lowes, Home Depot, Tractor Supply, Harbor Freight.

Writing instrument

Optional: (If you already have these then bring them, **otherwise they will be supplied**)

Arc welding jacket (leather or denim)

Any other arc welding clothing (leather or denim)

Full face arc welding helmet with a number 10 or 11 shade lens

Gas welding goggles with a number 5 shade lens

Do Not:

Wear Loafers or Sandals

Wear Shorts

Smoke at anytime in the studio

Revision 09-21-14